

Motorola 52nd Street Superfund Site-OU2 Update

Community Informational Group- June 22, 2011



Arizona Department of Environmental Quality



U.S. Environmental Protection Agency, Region 9





that exceed the Aquifer Water Quality Standards.

? - Insufficient Data

Drieuperfund/Phoenix/2010/M521. Projects/2010/M52-2010.5close mx


MOTOROLA 52ND STREET SUPERFUND SITE

PHOENIX, ARIZONA



Phoenix, Arizona

July, 2010





 ADEQ & EPA submitted comments on the Final Focused Honeywell Human Health Risk Assessment on June 9, 2011

 Next step is for Honeywell to prepare a Vapor Intrusion Indoor Air Technical Memorandum and then Feasibility Study Report



- OU2 Effectiveness Report for the Treatment Facility-currently under review
- Updated Operations & Maintenance Manualunder review for the Treatment Facility
- Quarterly Groundwater Monitoring Reports for the 20th Street Groundwater Treatment Facilityreviewed each quarter
- Quarterly Operations and Maintenance Activities Progress Report-reviewed each quarter



- Honeywell Area 13 and 21-Currently developing Administrative Order of Consent- close to completion
- Goal is to complete a Focused Remedial Investigation of each area



Contact Information

Brian Stonebrink

Project Manager- M52 OU2

Federal Projects Unit

Arizona Department of Environmental Quality

(602) 771-4197

Stonebrink.Brian@azdeq.gov